



- REVISIONS  
22/4/2011
- (a) Move disabled toilet to entry corridor and reshape ladies and gents W.C's
  - (b) Enhance escape route into walking area for kitchen
  - (c) Entry doors relocated from side to end of building
  - (d) Remove blue picket gates
  - (e) New windows to end of classroom and dining area
  - (f) Lighten building for extra toilets, classroom and provide cleaners sink and stores
  - (g) Internal sliding doors extended
  - (h) Resuscitation changes
  - (i) Building moved to East of plot to retain open landscape view when approaching from road and visual separation from lighthouse
  - (j) Adjust main floor level of building after projected flooding information
  - (k) Walkway altered for new building position
  - (l) Enclose lower area
  - (m) Steps added outside kitchen and emergency escape ramp to east end with raised soil bund to slope



Sir Peter Scott Centenary Centre  
East Bank Lighthouse, Sutton Bridge  
**Elevations**  
Drawing 2/lh/11  
SCALE 1:100  
22/4/2011